

Error memory

Date: 2024-10-29, 7:38 AM
VIN: 5UXFE83587LZ43519

12 Engine electronics

3 errors

2EBD: CDKBSDD6 0x2EBD - BSD message missing from generator

2E8B: CDKIBSK 0x2E8B - Intelligent battery sensor, signal

2DEB: CDKPMBN 0x2DEB - Power management, vehicle electrical system monitoring

27 Comfort Access

1 error

A06B: Stossfaengerantennen_defekt

29 Dynamic stability control EHB3

1 error

5E8C: 5E8C - PT-CAN: Message STATUS_ANHAENGER (ID 0x2E4) not received (received from DSC-SG). [Sender: AHM] --- (DSC: Message (trailer 2E4) is missing)

39 Vertical dynamics management

1 error

6310: HSensor signal VR

56 Roof function centre

1 error

A670: BSS fault signal line BSS 0xA670

56 Roof function centre

1 error

A670: BSS fault signal line BSS 0xA670

5E Gear selector switch

1 error

A82E: Locking system: lock Manual lane defective

77 Reversing camera

1 error

A811: Energy saving mode active

78 Automatic heating/air conditioning

1 error

E723: Message (KCAN: Status fitting disc V, 2D1)

29 Dynamic stability control EHB3

1 error

5E8C: 5E8C - PT-CAN: Message STATUS_ANHAENGER (ID 0x2E4) not received (received from DSC-SG). [Sender: AHM] --- (DSC: Message (trailer 2E4) is missing)